□□□ □□□ □□ □□, □□ □□, □□□ □□, □□ □□, □□ □□□□ □□, □ □, □□□ □□, □□□ □□, □□□ □□, □□□□ □□, □□□ □□ □□□ □□ □□ □ □□□□.□□ □□ □.

□□□ □□□□ □□□ □□ □□, □□□ □□ □□, □□ □□, □□ □□, □□ □□ □□ □ □□ □□ □□□ □□ □□□□□. □□□, □□, □□ □ □□□□□ □□ □□ □□ □□□ □ □□□□.□□ □□ □□□ □□ □ □ □ □□□ □□ □ □□ □□□□□ □□ □ □ □□□□.□□□ □□ □□□ □□□ □□□□□ □□□□□.

□□□ □□ □□ □□ □□ □□, □□□ □□ □ □□ □□□ □□□□ □□□ □□□□ □□□□.

□□□ □□□ □□ □□□ □□ □□□ □ □□ □□□ □□□ □ □□□□.

□□ □□□ □□ □□ □□ :

□□	□□□ □□	□□ □□	□□ □□ (□)	□□ (g/cm³) ± 0.1	□□ (HRA) ± 0.5	Trs (kgf/mm²)
HE10	94	6	1.6	14.95	90.4	> 300
HE15	94	6	2.0	14.95	89.6	> 280
HE16	94	6	3.2	14.95	88.2	> 270
HE20	92	8	3.2	14.75	87.8	> 270
HE30	91	9	3.2	14.65	87.5	> 260
He35	89	11	3.2	14.40	86.8	> 250
He36	88	12	2.0	14.30	87.0	> 280
He40	87	13	3.2	14.20	85.5	> 240
HE50	85	15	3.2	14.05	85.0	> 230
HAC3	94	6	4.0	14.95	88.3	> 240
TC02	91.5	8.5	6.0	14.65	86.4	> 240



Flat Buttons Types (P)

Suitable for cone bit, diamond bit,
Hole stabilizer, etc.
Reduce wear on the surface of steel pants.



Wedged Buttons Types(X)

Used for insert special-shaped submersible drill bit and cone bit,
Suitable for high speed,
A soft rock formation with a low incidence of broken teeth.



Inserts (Tips) for Coal bits and Mechanical Engineering Road-cutters birs(M)

Used for insert drilling bit, cone bit,
Suitable for coal mining or road surface mining.



Spoon (Scoop) Buttons Types(S)

Used for insert roller bit,
Suitable for soft rock formation drilling at high speed.